

ERA24FA058

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of main impact site. The airplane approached from right to left in the photograph.



Photograph 2 - View of debris field taken from main impact site looking up the hill at the debris field.



Photograph 3 - View of main impact site and wreckage debris field.



Photograph 4 - View of left elevator and vertical stabilizer.



Photograph 5 - View of approximate direction of travel taken from main impact site.



Photograph 6 - Hangar floor layout of wreckage looking aft.



Photograph 7 - View of left wing and landing gear during hangar floor layout.



Photograph 8 - View of right wing during hangar floor layout.